













Nordberg C106

Nr fabryczny 36647

KATALOG CZĘŚCI

	Profile szczęk kg (funtów)	Płyty policzkowe kg (funtów)	Płyta Płyta kg (funtów)	Koło zamachowe kg (funtów)	Zespół wahadła z profilami szczęki kg (funtów)	Rama krusarki kg (funtów)	Kompletna krusarka kg (funtów)
C80	575 (1268)	59 (130)	50 (110)	430 (950)	2870 (6310)	4630 (10190)	7660 (16890)
C96	885 (1950)	58 (128)	60 (132)	520 (1145)	3380 (7445)	4400 (9692)	9760 (21510)
C100	1460 (3219)	160 (353)	105 (231)	1200 (2646)	7060 (15560)	10200 (22490)	20100 (44230)
C106	1325 (2920)	85 (187)	96 (212)	796 (1755)	4910 (10825)	6625 (14606)	17600 (38801)
C110	950 (2094)	151 (333)	100 (220)	1640 (3615)	9000 (19840)	12700 (28000)	25800 (56860)
C116	1305 (2877)	85 (187)	116 (255)	977 (2153)	6531 (14399)	7091 (15633)	18500 (40770)
C125	1150 (2535)	301 (664)	187 (413)	2680 (5910)	12960 (28570)	18400 (40750)	37970 (83710)
C140	1470 (3241)	365 (805)	201 (443)	2700 (5952)	15950 (35160)	23600 (52030)	47120 (103880)
C145	1710 (3770)	260 (573)	225 (496)	3350 (7370)	18260 (40172)	21200 (46720)	54540 (120230)
C160	2240 (4938)	483 (1065)	350 (770)	3350 (7370)	23980 (52756)	41800 (91960)	76430 (168500)
C200	4090 (9017)	500 (1102)	490 (1080)	6500 (14300)	39700 (87520)	50400 (111100)	121500 (267880)
C3054	1940 (4277)	94 (207)	127 (280)	1460 (3220)	9490 (20920)	9540 (21020)	25900 (57100)

Tabela 3-1 Masy kruszarki i podzespołów

zagrożeń należy postępować ostrożnie i przestrzegać procedur podnoszenia.
Należy stosować wyłącznie odpowiednie,